## **EAST Search History**

Ref#	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	3018	tack near3 (measur\$4 or test\$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 09:57
L2	906804	(driv\$3 or excit\$3 or actuat \$3) near5 (cylinder or roller or wheel)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 09:57
L3	990907	(force or stress or strain or pressure or load) near3 (transducer or gauge or gage or sens\$3 or detect \$3 or determin\$3 or indicat \$3 or cell)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 09:59
L4	33	1 and 2 and 3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 10:12
L5	48966	(tack or stick\$3 or adhesive or adhesion) near3 (measur\$4 or test \$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 10:17
L6	33	4 and 2 and 3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 10:17
L7	50100	((tack or stick\$3 or stickiness or cohesiv\$5 or adhesive or adhesion) near3 (measur\$4 or test \$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 10:29
L8	989451	(driv\$3 or excit\$3 or actuat \$3 or power\$3) near5 (cylinder or roller or wheel)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 10:30

_9	402	7 and 8 and 3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 10:34
L10	17573	(florce or stress or strain or pressure or load) near3 (transducer or gauge or gage or sens\$3 or detect \$3 or determin\$3 or indicat \$3 or cell) near7 (integrat \$3 or attach\$3 or connect\$3 or onnect\$3 or coupl\$3) near15 (roller or cylinder or wheel or fram\$3 or hous \$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 10:45
L12	20	9 and 10	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17
L13	17633	(florce or stress or strain or pressure or load or pressure or load or piezoelectic\$3 or (piezo near3 electric\$4) near3 (transducer or gauge or gage or sens\$3 or detect \$3 or determin\$3 or indicat \$3 or catlach\$3 or atflix\$3 or connect\$3 or coupl\$3) near15 (roller or cylinder or wheel or fram\$3 or hous \$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 10:57
L14	21	9 and 13	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 10:59
L15	12	(73/150A).CCLS.	US-PGPUB	OR	OFF	2008/03/17 11:03
L16	197	(73/150A).CCLS.	USPAT; USOCR	OR	OFF	2008/03/17 11:03

L17	161520	(force or stress or strain or pressure or load or piezoelectic\$3 or (piezo near3 electric\$4)) near3 (transducer or gauge or gage or sens\$3 or detect \$3 or determin\$3 or indicat \$3 or cell) near7 (integrat \$3 or connect\$5 or coupt\$5) or connect\$5 or coupt\$5)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	MOR		2008/03/17 11:09
L18	85	9 and 17	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 11:12
L19	138823	(driv\$3 or excit\$3 or actuat \$3) near5 (roll)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 11:34
L20	530	19 and 7	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 11:35
L22	20	17 and 20	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 11:37
L23	438	(73/150R).CCLS.	US-PGPUB; USPAT	OR	OFF	2008/03/17 11:40
L24	14	23 and 17	US-PGPUB; USPAT	OR	ON	2008/03/17 11:41
L25	1686	(force or stress or strain or pressure or load or piezoelectic\$3 or (piezo near3 electric\$4) near3 (transducer or gauge or gage or sens\$3 or detect \$3 or determin\$3 or indicat \$3 or cell) near7 (integrat \$3 or attach\$3 or affix\$3 or connect\$3 or coupl\$3) near30 pivot\$4	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 11:52

L26	6	7 and 25	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 11:54
_27	1943	(force or stress or strain or pressure or load or pressure or load or piezoelectic\$3 or (piezo near3 electric\$4) near3 (transducer or gauge or gage or sens\$3 or detect \$3 or determins3 or indicat \$3 or call) near7 (integrat \$3 or attach\$3 or affix\$3 or connect\$3 or coupl\$3) near30 bearing	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 12:21
_28	18	27 and 7	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 12:23
L29	33	(73/54.22).CCLS.	US-PGPUB; USPAT	OR	OFF	2008/03/17 12:35
L32	52085	(tack or stick\$3 or adhesive or adhesion) near3 (measur\$4 or test\$3 or monitor\$3 or analysis or analyz\$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 13:14
_33	502	(ink or print\$3) near3 (roll or roller or cylinder or conduit or rod or cylinder or conduit or rod or cylinder or pip\$3 or wheel) with ((force or stress or strain or pressure or load or piezoelectic\$3 or (piezo near3 electric\$4)) near3 ((transducer or gauge or gage or sens\$3 or detect \$3 or determin\$3 or indicat \$3 or cell))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 13:14
L34	9	32 and 33	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 13:15

L35	3	inkometer\$3 and 33	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 13:27
L36	2662	inkometer\$3 or ((ink or inko) near3 meter\$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 13:29
L37	27	36 and 17	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 13:33
L38	7	(inkometer\$3 or ((inko) near\$ meter\$3) and (flore or stress or strain or pressure or load or piezoelectic\$3 or (piezo near\$ electric\$4) near\$ (transducer or gauge or gage or sens\$3 or determis\$3 or indicat \$3 or cell)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 13:40
L39	996012	(force or stress or strain or pressure or load or piezoelectic\$3 or (piezo near3 electric\$41) near3 (transducer or gauge or gage or sens\$3 or detect \$3 or determin\$3 or indicat \$3 or cell)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 13:48
L40	7654	7 and 39	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 13:50
L41	12906	(force or stress or strain or pressure or load or piezoelectic\$3 or (piezo near3 electric\$4)) near3 (transducer or gauge or gage or sens\$3 or detect \$3 or determin\$3 or indicat \$3 or cell) near15 bearing	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 13:52

L42	70	7 and 41	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/17 14:00
S1	7	(("2,101322") or ("2,762,219") or ("3,368,399") or ("3,531986") or ("4,294,111") or ("5,388,442") or ("20020194895")).PN.	US-PGPUB; USPAT	OR	OFF	2008/03/15 10:02
S3	567110	(driv\$3 or excit\$3 or actuat \$3) near5 (cylinder or roller)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/15 10:34
S4	3843	(couple or multiple or plural \$3 or second or two) near3 (cylinder or roller) with ((pressure or stress or strain or load or force) near3 (cell or sens\$3 or detect\$3 or transducer or gage or gauge or indicat \$3 or measus\$4))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/15 10:35
S5	1615	S3 and S4	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/15 10:36
S6	3017	tack near3 (measur\$4 or test\$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/15 10:36
S7	3	S5 and S6	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/15 10:37
S9	20	S5 and (yoke near7 (fram \$3 or hous\$3))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/15 10:42

S10	10	S5 and ((movable or moving or pivot\$3) near5 yoke near7 (roller or cylinder))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/15 10:48
S11	10	S5 and ((movable or moving or movably or pivot \$3) near5 yoke near7 (roller or cylinder))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/15 10:49
S12	1391	yoke near7 (roller or cylinder) near7 bearing	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/15 11:03
S13	5	S5 and S12	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/15 11:04
S14	7	"5388422"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/15 11:14
S17	1	("5388442").PN.	US-PGPUB; USPAT	OR	OFF	2008/03/15 11:14
S18	0	S17 and yoke	US-PGPUB; USPAT	OR	ON	2008/03/15 11:15

## 3/17/08 2:08:43 PM

C:\Documents and Settings\TBellamy\My Documents\EAST\workspaces\10551076.wsp